

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

2901 E. COLORADO ST., PASADENA, CALIF.

No. 11768

RECEIVED FROM

Approved For Release 2000/04/18 : CIA RDP81B00879R000500080218-2

DATE REC'D.

P.O. NO.

VENDOR PACKING SLIP NO.

 ACCT. OR W.O. NO.

S.O. NO.

REMARKS

CHARGE TO
QUANTITY
RECEIVED

CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT COST NO.	
322	600100	80	A	19	1			
DRAWING NO. AND DESCRIPTION				QUANTITY				REMARKS
5	735451-039	Combination Lock Master #1500	Stamp 677764		5			<i>H. J. Storer</i>

RECEIVED

INSPECTED
BY

HMC-1068

DATE 4-2-57

REJECTS RETURNED
ON SHIP. MEMO NO.

RECEIVED FROM

RECEIVING INSPECTION REPORT
HYCON MFG. COMPANY
2901 E. COLORADO ST., PASADENA, CALIF.

No. 11767

DATE REC'D.

P.O. NO.

VENDOR PACKING SLIP NO.

 ACCT. OR W.O. NO.

S.O. NO.

REMARKS

CHARGE TO
QUANTITY
RECEIVED

CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT COST NO.	
322	600100	55	B	43				
DRAWING NO. AND DESCRIPTION				QUANTITY				REMARKS
4	735451-014	Tweezers, Ductile #12			4			<i>H. J. Storer</i>

RECEIVED
BY

Approved For Release 2000/04/18 : CIA RDP81B00879R000500080218-2

HMC-1068

DATE

REJECTS RETURNED
ON SHIP. MEMO NO.